

October 15, 1979

NOAA DIVING SAFETY BULLETIN #79-5

MEMORANDUM FOR: ALL NOAA DIVERS

FROM: J. Morgan Wells
NOAA Diving Coordinator

SUBJECT: Recall of Dacor Pacer Regulators and Repair of Regulators

Communication with representatives of the Dacor Corporation has prompted the following statement:

To All Dacor PACER Regulator Owners

Dacor Corporation has announced a voluntary Recall of all PACER regulators and second Stages shipped from the factory prior to July 31, 1979. A flaw which occurred during Fabrication has been discovered in the top Cover of the second state and can cause free Flow. All PACER owners who suspect they have A faulty unit, should not dive with the Regulator and should take it to their nearest Dacor dealer for free repair. Because of a Design modification, PACER regulators shipped after August 1, 1979, are not involved in this recall.

The following attachments outline in detail to the Dacor dealer the details of repair pertaining to the recall of the PACER regulators, and instructions for cover assembly.

It is the feeling of the NOAA Diving Office that the preceding repair directions be carried out by an authorized Dacor Dealer or an authorized repair facility.

Attachment