

October 11, 1989

NOAA Diving Safety Bulletin 89-2

MEMORANDUM FOR: All NOAA Divers

FROM: Cliff Newell
Deputy NOAA Diving Coordinator

SUBJECT: Dacor Regulator Recall

We have recently learned that Dacor Corporation issued a recall notice to their dealers in January 89.

Discussion with Dacor personnel indicates that failure of the second stage lever causes a stoppage of air flow to the diver. Please review the attached Dacor report to ensure that you are not using a suspect unit.