

June 9, 1988

NOAA DIVING SAFETY BULLETIN 88-1

MEMORANDUM FOR: ALL NOAA DIVERS

FROM: N/MO15 - J. Morgan Wells
NOAA Diving Coordinator

SUBJECT: Recall Bulletin Concerning Scubapro
Heat-Sealed Type Stabilizing Jackets
and Front Adjustable Buoyancy Devices

The NOAA Diving Program Office has been notified of a potential problem with the overpressure/dump valve on the Heat-Sealed Type Scubapro Buoyancy Devices.

Scubapro is voluntarily recalling all of its Heat-Sealed Type Buoyancy Devices manufactured prior to April 28, 1988.

All NOAA divers will suspend the use of this buoyancy device until the valve has been replaced by Scubapro or an authorized Scubapro dealer, and the valve has been tested.

The attached information concerning the recall procedures should be followed to ensure the proper repair of this buoyancy device.

NOAA Diving Program Point of Contact:

Chet Stanley - Diving Training Instructor
NOAA Diving Program Headquarters
WSC-1 Rm. 304, 6001 Exec. Blvd.
Rockville, Maryland 20852
FTS 443-8007 Commercial (301) 443-8007

Attachment